FAST SEAL 5' AND 8' "T-O" LOCKING PROCEDURE




Diagram A




Diagram B



Diagram C

STEP 1

Make sure the seal flap is held with the rear side facing the user as shown in diagram A.

STEP 2

Hold the seal flap using one hand and with the other, insert the strip at the entry hole (follow the arrows for guidance) as shown in diagram B. After inserting, pull the strip to maximum tightness and ensure there is no gap left after sealing it.

STEP 3

To tear off or remove the seal, hold the seal flap using one hand and with the other, pull at the tear-off section of the seal as shown in Diagram C.